Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZDU003875

Odometer Reading: 239503
License Plate: CB18FKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
01 - Engine Control Module 1	3
03 - Brakes 1	0
08 - Air conditioning	1
09 - Electronic central electric	1
15 - Airbag	1
17 - Instrument cluster	2
19 - Gateway	0
25 - Immobilizer	0
44 - Power steering	2
46 - Comfort System Central Control Module	1
56 - Radio	0

DTC (11)

01 - Engine Control Module 1 (3 DTCs)

DTC	Description	Status
16711:000	Knock Sensor 1 Circ. Low Input	Passive/Sporadic
16514:000	O2 Sensor Circ.,Bank1-Sensor1 Malfunction	Passive/Sporadic
18049:000	Read DTC memory of A/C control module	Active/static

08 - Air conditioning (1 DTC)

DTC	Description	Status

00819:007	High pressure sensor - Signal too low	Active/static

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:027	Drive battery voltage - Implausible signal	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
01316:049	Brake control module - No communication	Passive/Sporadic
00457:049	Vehicle Electrical System Control Module - No communication	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

46 - Comfort System Central Control Module (1 DTC)

DTC	Description	Status
01330:053	Comfort system central control module - Voltage supply too low	Passive/Sporadic

Technician Notes

2017317658

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.