Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZFU015228

Odometer Reading: 218015
License Plate: JNG860NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	5
03 - Brakes 1	4
09 - Electronic central electric	2
15 - Airbag	1
17 - Instrument cluster	2
19 - Gateway	1
25 - Immobilizer	0
44 - Power steering	3
46 - Comfort System Central Control Module	1
56 - Radio	3

DTC (22)

01 - Engine Control Module 1 (5 DTCs)

DTC	Description	Status
P0571:00/01 393:000	Cruise/Brake Switch (A) Circ. Malfunction	Active/static
P1570:00/05 488:000	Engine control unit disabled	Passive/Sporadic
P1672:00/05 746:000	Fan 1 control circuit Open circuit/short circuit to ground	Passive/Sporadic
P0300:00/00 768:000	Random/Multiple Cylinder Misfire Detected	Passive/Sporadic
P0303:00/00 771:000	Cyl.3 Misfire Detected	Passive/Sporadic

03 - Brakes 1 (4 DTCs)

DTC	Description	Status
00283:012	Left front ABS wheel speed sensor - Electrical error in circuit	Active/static
00290:012	Left rear ABS wheel speed sensor - Electrical error in circuit	Active/static
00526:011	Brake light switch - Open circuit	Passive/Sporadic
01201:000	ABS pump voltage supply	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
01598:027	Drive battery voltage - Implausible signal	Passive/Sporadic
01309:049	Power steering control module - No communication	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
65535:000	Ctrl. module faulty	Active/static
01309:049	Power steering control module - No communication	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01309:049	Power steering control module - No communication	Passive/Sporadic

44 - Power steering (3 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
U140A00	Terminal 30 ,Open circuit	Passive/Sporadic
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

46 - Comfort System Central Control Module (1 DTC)

DTC	Description	Status
01330:053	Comfort system central control module - Voltage supply too low	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
00852:044	Front speaker(s) - Short circuit	Active/static
00853:036	Rear speaker(s) - Open circuit	Active/static
01044:025	Control module incorrectly coded - Undefined switch condition	Active/static

Technician Notes

2017317853

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.