**Shop Name:** –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261001143849
Test Time: 2026-10-01 14:38:49
Technician: Travino

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZHU031718

Odometer Reading: 172859
License Plate: KWR068NW

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 9 )

| System | Status/DTC |
|---|---|
| 01 - Engine Control Module 1 | 0 |
| 03 - Brakes 1 | 1 |
| 09 - Electronic central electric | 2 |
| 15 - Airbag | 1 |
| 17 - Instrument cluster | 1 |
| 19 - Gateway | 1 |
| 25 - Immobilizer | 0 |
| 44 - Power steering | 3 |
| 46 - Comfort System Central Control Module | 2 |

## DTC ( 11 )

### 03 - Brakes 1 ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| 00532:002 | Supply voltage - Lower limit not reached | Passive/Sporadic |

### 09 - Electronic central electric ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| 01598:027 | Drive battery voltage - Implausible signal | Active/static |
| 01309:049 | Power steering control module - No communication | Passive/Sporadic |

### 15 - Airbag ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| 00532:007 | Supply voltage - Signal too low | Passive/Sporadic |

### 17 - Instrument cluster ( 1 DTC )

| DTC | Description | Status |
|---|---|---|

| | | |
|---|---|---|
| 01309:049 | Power steering control module - No communication | Passive/Sporadic |

## 19 - Gateway ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| 01309:049 | Power steering control module - No communication | Passive/Sporadic |

## 44 - Power steering ( 3 DTCs )

| DTC | Description | Status |
|---|---|---|
| U140000 | Function restriction due to low voltage | Passive/Sporadic |
| U140A00 | Terminal 30 Open circuit | Passive/Sporadic |
| U101100 | Supply voltage Voltage too low | Passive/Sporadic |

## 46 - Comfort System Central Control Module ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| 01330:053 | Comfort system central control module - Voltage supply too low | Passive/Sporadic |
| 00849:025 | S-contact at ignition starter switch - Undefined switch condition | Active/static |

## Technician Notes

2017305827

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*