Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZJU041121

Odometer Reading: 180027km
License Plate: HM18HCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
01 - Engine Control Module 1	4
02 - Transmission electronics	6
03 - Brakes 1	3
08 - Air conditioning	0
09 - Electronic central electric	2
15 - Airbag	2
17 - Instrument cluster	2
19 - Gateway	3
44 - Power steering	1
5F - Information electronics 1	1
76 - Parking aid ADAS	2
CA - Sunroof control module	1

DTC (27)

01 - Engine Control Module 1 (4 DTCs)

DTC	Description	Status
P305400	Starter does not turn ,Mechanically blocked or electrical malfunction	Active/static
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
U102600	Transmission control module ,Check event memory	Passive/Sporadic
P157000	Engine control unit disabled	Passive/Sporadic

02 - Transmission electronics (6 DTCs)

DTC	Description	Status
P278900	Clutch adaptive learning at limit	Passive/Sporadic
P177B00	Clutch 1 ,Tolerance limit reached	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
P189A00	Clutch 1 ,Clearance too small	Active/static
P056200	System Voltage ,Low Voltage	Passive/Sporadic
P0B0A00	Auxiliary Transmission Fluid Pump Motor ,supply voltage Circuit Low	Passive/Sporadic

03 - Brakes 1 (3 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
C102D00	Tire pressure warning	Active/static
C106A16	ABS valves voltage supply ,Voltage too low	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B147918	Remote control vehicle key 1 ,Insufficient current	Active/static

15 - Airbag (2 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
B13BCF2	Multiple collision brake ,No function	Active/static

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
B201000	No basic setting	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140600	Static current ,too high	Passive/Sporadic
B1802F1	NV-Energy management ,Alarm triggered	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

76 - Parking aid (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

CA - Sunroof control module (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

Technician Notes

2017310667

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.