

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--  
VIN: AAVZZZAWZJU049633

Odometer Reading: 81367km  
License Plate: FVW163L

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V25.00

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned ( 10 )

| System                           | Status/DTC                                                                              |
|----------------------------------|-----------------------------------------------------------------------------------------|
| 01 - Engine Control Module 1     |  14  |
| 03 - Brakes 1                    |  1   |
| 08 - Air conditioning            |  1   |
| 09 - Electronic central electric |  8   |
| 15 - Airbag                      |  1 |
| 17 - Instrument cluster          |  3 |
| 19 - Gateway                     |  1 |
| 44 - Power steering              |  0 |
| 5F - Information electronics 1   |  2 |
| CA - Sunroof control module      |  2 |

## DTC ( 33 )

### 01 - Engine Control Module 1 ( 14 DTCs )

| DTC     | Description                                                             | Status           |
|---------|-------------------------------------------------------------------------|------------------|
| P308800 | Starter relay<br>Electrical fault in circuit                            | Passive/Sporadic |
| P305400 | Starter does not turn<br>Mechanically blocked or electrical malfunction | Passive/Sporadic |
| U111300 | Function limitation due to received malfunction value                   | Passive/Sporadic |
| U101700 | ABS Control Module<br>Check event memory                                | Passive/Sporadic |
| P190D00 | Coolant pump for charge pressure cooler<br>Mechanical malfunction       | Passive/Sporadic |

|         |                                                             |                  |
|---------|-------------------------------------------------------------|------------------|
| P151B00 | Voltage terminal 15<br>Implausible                          | Passive/Sporadic |
| U043100 | Invalid data received from body control module A            | Passive/Sporadic |
| P210600 | Throttle Actuator Control System<br>Forced Limited Power    | Passive/Sporadic |
| P154500 | Throttle valve control system<br>Malfunction                | Passive/Sporadic |
| P034100 | Camshaft Position Sensor<br>Implausible signal              | Passive/Sporadic |
| P008700 | Fuel rail/system pressure - too low                         | Passive/Sporadic |
| P068A00 | ECM/PCM Power Relay De-Energized Performance - Too<br>Early | Passive/Sporadic |
| P157000 | Engine control unit disabled                                | Passive/Sporadic |
| P125000 | Fuel level<br>too low                                       | Passive/Sporadic |

**03 - Brakes 1 ( 1 DTC )**

| DTC     | Description           | Status        |
|---------|-----------------------|---------------|
| C102D00 | Tire pressure warning | Active/static |

**08 - Air conditioning ( 1 DTC )**

| DTC     | Description                                | Status           |
|---------|--------------------------------------------|------------------|
| U140000 | Function restriction<br>due to low voltage | Passive/Sporadic |

**09 - Electronic central electric ( 8 DTCs )**

| DTC     | Description                                              | Status           |
|---------|----------------------------------------------------------|------------------|
| B12BF15 | Right tail lamp bulb<br>Open circuit/short circuit to B+ | Passive/Sporadic |
| B12CA15 | License plate lamp<br>Open circuit/short circuit to B+   | Passive/Sporadic |
| U101100 | Supply voltage<br>Voltage too low                        | Passive/Sporadic |
| B147A18 | Remote control vehicle key 2<br>Insufficient current     | Passive/Sporadic |
| B133029 | Anti-theft alarm system sensor<br>Range/performance      | Active/static    |
| B131F54 | Driver side rear window regulator<br>No basic setting    | Passive/Sporadic |
| B132054 | Passenger side rear window regulator<br>No basic setting | Passive/Sporadic |

|         |                             |                  |
|---------|-----------------------------|------------------|
| U110100 | Component protection active | Passive/Sporadic |
|---------|-----------------------------|------------------|

15 - Airbag ( 1 DTC )

| DTC     | Description                             | Status           |
|---------|-----------------------------------------|------------------|
| B13BCF2 | Multiple collision brake<br>No function | Passive/Sporadic |

17 - Instrument cluster ( 3 DTCs )

| DTC     | Description                       | Status           |
|---------|-----------------------------------|------------------|
| U101100 | Supply voltage<br>Voltage too low | Passive/Sporadic |
| B104B31 | Key<br>No signal                  | Passive/Sporadic |
| B104C29 | Key<br>Range/performance          | Passive/Sporadic |

19 - Gateway ( 1 DTC )

| DTC     | Description                       | Status           |
|---------|-----------------------------------|------------------|
| U101100 | Supply voltage<br>Voltage too low | Passive/Sporadic |

5F - Information electronics 1 ( 2 DTCs )

| DTC     | Description                                | Status           |
|---------|--------------------------------------------|------------------|
| U140000 | Function restriction<br>due to low voltage | Passive/Sporadic |
| B106513 | Left rear bass speaker<br>Open circuit     | Active/static    |

CA - Sunroof control module ( 2 DTCs )

| DTC     | Description                         | Status           |
|---------|-------------------------------------|------------------|
| U101100 | Supply voltage<br>Voltage too low   | Passive/Sporadic |
| B13C429 | Sunroof button<br>Range/performance | Passive/Sporadic |

Technician Notes  
2017303555

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.