Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZLU014177

Odometer Reading: 195472km
License Plate: LY53VPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
01 - Engine Control Module 1	8
02 - Transmission electronics	2
03 - Brakes 1	5
08 - Air conditioning	0
09 - Electronic central electric	0
15 - Airbag	1
17 - Instrument cluster	2
19 - Gateway	4
44 - Power steering	2
5F - Information electronics 1	2
76 - Parking aid	0
CA - Sunroof control module	2

DTC (28)

01 - Engine Control Module 1 (8 DTCs)

DTC	Description	Status
P308800	Starter relay Electrical fault in circuit	Passive/Sporadic
P305400	Starter does not turn Mechanically blocked or electrical malfunction	Active/static
P030000	Random Misfire Detected No Sub Type Information	Passive/Sporadic

P030100	Cylinder 1 Misfire Detected No Sub Type Information	Passive/Sporadic
P030200	Cylinder 2 Misfire Detected No Sub Type Information	Passive/Sporadic
P030300	Cylinder 3 Misfire Detected No Sub Type Information	Passive/Sporadic
P130A00	Cylinder suppression	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Active/static

02 - Transmission electronics (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
P056200	System Voltage Low Voltage	Passive/Sporadic

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
C106A16	ABS valves voltage supply Voltage too low	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic
C10A800	Wheel diameter implausible	Active/static
C102D00	Tire pressure warning	Active/static
C10A416	Low pressure sensor power supply Voltage too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
B104B31	Key No signal	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

19 - Gateway (4 DTCs)

DTC	Description	Status

U101100	Supply voltage Voltage too low	Passive/Sporadic
U140600	Static current too high	Passive/Sporadic
U141100	Battery terminal recognition Open circuit	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U11B800	Interface for external media No communication	Active/static

CA - Sunroof control module (2 DTCs)

DTC	Description	Status
B157429	Button for sliding roof Range/performance	Passive/Sporadic
U112200	Data bus message implausible	Passive/Sporadic

Technician Notes

2017318924

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.