Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZLU035456

Odometer Reading: 252440km
License Plate: KTS844NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
01 - Engine Control Module 1	52
03 - Brakes 1	5
08 - Air conditioning	2
09 - Electronic central electric	17
17 - Instrument cluster	5
19 - Gateway	4
44 - Power steering	4
5F - Information electronics 1	8

DTC (97)

01 - Engine Control Module 1 (52 DTCs)

DTC	Description	Status
P15A100	Transmission gear N sensor ,Signal implausible	Passive/Sporadic
P15AA00	Engine oil pressure ,Below lower limit	Passive/Sporadic
P019700	Oil temperature sensor ,Short circuit to ground	Active/static
P159D00	Oil level/temperature sensor ,Range/performance	Passive/Sporadic
P159D00	Oil level/temperature sensor ,Range/performance	Active/static
P15A600	Control deviation, oil pressure control ,Above upper limit	Active/static
P305400	Starter does not turn ,Mechanically blocked or electrical malfunction	Passive/Sporadic
P229400	Fuel Pressure Regulator 'B' Control Circuit/Open	Passive/Sporadic
U102500	Climate Control Module ,Check event memory	Passive/Sporadic
U100800	Data bus diagnostic interface ,Check event memory	Passive/Sporadic
U11EF00	Sensor/switch 1 for engine oil pressure ,No communication	Passive/Sporadic

P164E00	Oil pressure regulation valve ,Electrical error	Passive/Sporadic
P029900	Turbocharger/supercharger underboost	Active/static
P165F00	Oil pressure regulation valve ,Short circuit to ground	Active/static
P050100	Vehicle speed sensor A ,Range/performance	Passive/Sporadic
P16BA00	Charge pressure cooler coolant pump ,Dry run	Passive/Sporadic
U012100	Lost Communication With ,Anti-Lock Brake System (ABS) Control Module	Passive/Sporadic
P15A000	Neutral position sensor ,Electrical error	Passive/Sporadic
U101700	ABS Control Module ,Check event memory	Passive/Sporadic
U045200	Invalid data received from restraints control unit	Passive/Sporadic
U041500	Invalid data received from ,ABS control unit	Passive/Sporadic
U015100	Lost Communication With Restraints Control Module	Active/static
P050700	Idle control system ,Speed higher than specified value	Passive/Sporadic
P209000	Bank 1, camshaft adjustment, exhaust ,Short circuit to ground	Passive/Sporadic
P105700	Bank 1, camshaft adjustment, exhaust ,Open circuit	Active/static
P001400	B Camshaft Position (Bank1) ,Timing over-advanced or System Performance	Active/static
P055600	Brake booster pressure sensor circuit range/performance	Passive/Sporadic
P012200	Throttle/pedal position sensor/switch A ,Circuit low	Passive/Sporadic
P022200	Throttle/pedal position sensor/switch B low input	Passive/Sporadic
P011700	Coolant temperature sensor 1 ,Circuit low	Passive/Sporadic
P208800	Bank1, camshaft adjustment ,Short circuit to ground	Active/static
P001000	'A' Camshaft Position Actuator Circuit/Open (Bank1)	Passive/Sporadic
P000A00	A Camshaft Position (CMP) slow response (bank 1)	Passive/Sporadic
P001100	A Camshaft Position (Bank1) ,Timing over-advanced or System Performance	Active/static
P034200	Camshaft Position Sensor ,Short circuit to ground	Passive/Sporadic
P036700	Camshaft position sensor exhaust bank 1 ,Short circuit to ground	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P227900	Intake air system leakage	Passive/Sporadic
P030000	Random Misfire Detected ,No Sub Type Information	Active/static
P030100	Cylinder 1 Misfire Detected ,No Sub Type Information	Passive/Sporadic
P030200	Cylinder 2 Misfire Detected ,No Sub Type Information	Active/static
P030300	Cylinder 3 Misfire Detected ,No Sub Type Information	Passive/Sporadic

P130A00	Cylinder suppression	Active/static
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Passive/Sporadic
P023800	Turbocharger boost sensor (A) circuit ,High input	Passive/Sporadic
P014800	Fuel Delivery Error	Active/static
P125000	Fuel level ,too low	Active/static
P011300	Intake air temperature sensor 1 (bank 1) ,Circuit high	Passive/Sporadic
P044100	EVAP Emission Contr.Sys.Incorrect ,Purge Flow	Active/static
P045800	Evaporative Emission (EVAP) system purge control valve A circuit short	Active/static
P044400	Evaporative Emission (EVAP) system purge control valve A circuit open	Passive/Sporadic
P056200	System Voltage ,Low Voltage	Passive/Sporadic

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
U015100	Lost Communication With Restraints Control Module	Active/static
C106A16	ABS valves voltage supply ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
B13BCF2	Multiple collision brake ,No function	Active/static
C10A416	Low pressure sensor power supply ,Voltage too low	Passive/Sporadic

08 - Air conditioning (2 DTCs)

DTC	Description	Status
B109211	Recirculation flap motor ,Circuit short to ground	Passive/Sporadic
U112100	Data bus message missing	Active/static

09 - Electronic central electric (17 DTCs)

DTC	Description	Status
B121D15	Left DRL bulb ,Circuit open or short to positive	Active/static
B12E815	Left side marker lamp bulb ,Open circuit/short circuit to B+	Active/static
B12E911	Right side marker lamp bulb ,Short circuit to ground	Active/static
B12BF15	Right tail lamp bulb ,Open circuit/short circuit to B+	Active/static
B12CA15	License plate lamp ,Open circuit/short circuit to B+	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U12AE00	Switching off control modules ,by knockout meter	Passive/Sporadic
B167929	Driver central locking lock unit ,Range/performance	Active/static
B167901	Driver central locking lock unit ,Electrical error	Passive/Sporadic

B131DF7	Sirens / alarm horn for anti-theft warning system ,No release by immobilizer	Passive/Sporadic
B131DF5	Sirens/alarm horn for anti-theft warning system ,Voltage supply below lower limit	Passive/Sporadic
B1468F0	Return message regarding driver door closing condition , Implausible	Passive/Sporadic
B126515	Heated rear window activation ,Open circuit/short circuit to B+	Active/static
U112100	Data bus message missing	Active/static
B14D1F5	Front driver window regulator ,Supply voltage below lower limit	Passive/Sporadic
B131529	Driver side window regulator control unit , Range/performance	Active/static
B14D254	Window regulator front passenger side ,No basic setting	Active/static

17 - Instrument cluster (5 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B103E1B	Fuel level sensor 1 ,Resistance too high	Passive/Sporadic
U112100	Data bus message missing	Active/static
B104B31	Key ,No signal	Passive/Sporadic
B104C29	Key ,Range/performance	Passive/Sporadic

19 - Gateway (4 DTCs)

DTC	Description	Status
U015100	Lost Communication With Restraints Control Module	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B1802F1	NV-Energy management ,Alarm triggered	Passive/Sporadic
U141100	Battery terminal recognition ,Open circuit	Active/static

44 - Power steering (4 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (8 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

U140000	Function restriction ,due to low voltage	Passive/Sporadic
B106213	Right front bass speaker ,Open circuit	Active/static
B106413	Right front treble speaker ,Open circuit	Active/static
B105F13	Left front bass speaker ,Open circuit	Active/static
B106113	Left front treble speaker ,Open circuit	Active/static
U112100	Data bus message missing	Active/static
U11B800	Interface for external media ,No communication	Passive/Sporadic

Technician Notes

2017326458

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.