

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZMU060202

Odometer Reading: 216250km
License Plate: JY31DZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
01 - Engine Control Module 1	 2
02 - Transmission electronics	 3
03 - Brakes 1	 1
08 - Air conditioning	 0
09 - Electronic central electric	 2
15 - Airbag	 0
17 - Instrument cluster	 2
19 - Gateway	 1
44 - Power steering	 1
5F - Information electronics 1	 3
CA - Sunroof control module	 1

DTC (16)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
P256400	Turbocharger boost control position sensor circuit low	Active/static
P042000	Catalyst System Efficiency Below Threshold Bank 1 No Sub Type Information	Passive/Sporadic

02 - Transmission electronics (3 DTCs)

DTC	Description	Status
P177B00	Clutch 1 Tolerance limit reached	Passive/Sporadic

U140000	Function restriction due to low voltage	Passive/Sporadic
P189A00	Clutch 1 Clearance too small	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
B12DD15	Rear lid Central Locking System Motor Open circuit/short circuit to B+	Passive/Sporadic
B131DF5	Sirens/alarm horn for anti-theft warning system Voltage supply below lower limit	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U111000	Function restriction due to communication interruption	Passive/Sporadic
B104B31	Key No signal	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
B106513	Left rear bass speaker Open circuit	Active/static
B10CD00	Function restriction caused by energy management	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic

CA - Sunroof control module (1 DTC)

DTC	Description	Status
U112200	Data bus message implausible	Passive/Sporadic

Technician Notes

2017302310

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.