Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261007102338
Test Time: 2026-10-07 10:23:38
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZMU064954

Odometer Reading: 64818km
License Plate: LL73CHGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
01 - Engine Control Module 1	6
02 - Transmission electronics	2
03 - Brakes 1	5
08 - Air conditioning	1
09 - Electronic central electric	12
15 - Airbag	1
17 - Instrument cluster	5
19 - Gateway	4
44 - Power steering	4
5F - Information electronics 1	3
76 - Parking aid ADAS	2
CA - Sunroof control module	1

DTC (46)

01 - Engine Control Module 1 (6 DTCs)

DTC	Description	Status
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
P218100	Cooling system performance	Passive/Sporadic
P332500	Voltage supply Kl.15 ,implausible	Passive/Sporadic
P308100	Engine temperature too low	Passive/Sporadic
P030000	Random Misfire Detected ,No Sub Type Information	Passive/Sporadic
P030100	Cylinder 1 Misfire Detected ,No Sub Type Information	Passive/Sporadic

02 - Transmission electronics (2 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
P056200	System Voltage ,Low Voltage	Passive/Sporadic

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
C106A16	ABS valves voltage supply ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
B13BCF2	Multiple collision brake ,No function	Passive/Sporadic
U016700	Lost Communication With Vehicle Immobilizer Control Module	Passive/Sporadic
C10A416	Low pressure sensor power supply ,Voltage too low	Passive/Sporadic

08 - Air conditioning (1 DTC)

DTC	Description	Status
B109211	Recirculation flap motor ,Circuit short to ground	Passive/Sporadic

09 - Electronic central electric (12 DTCs)

DTC	Description	Status
B121F15	Left fog lamp bulb ,Circuit open or short to positive	Active/static
B12E915	Right side marker lamp bulb ,Open circuit/short circuit to B+	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B131DF7	Sirens / alarm horn for anti-theft warning system ,No release by immobilizer	Passive/Sporadic
B131DF5	Sirens/alarm horn for anti-theft warning system ,Voltage supply below lower limit	Passive/Sporadic
B131D04	Sirens/alarm horn for anti-theft warning system ,Faulty	Passive/Sporadic
U10F300	Sirens / alarm horn for anti-theft warning system ,No communication	Active/static
B131D29	Sirens/alarm horn for anti-theft warning system , Range/performance	Active/static
B131FF5	Driver side rear window regulator ,Voltage supply below lower limit	Passive/Sporadic
B1320F5	Passenger side rear window regulator ,Voltage supply below lower limit	Passive/Sporadic
B14D154	Front window regulator, driver side ,No basic setting	Active/static
U111400	Component protection ,GFA key	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake ,No function	Passive/Sporadic

17 - Instrument cluster (5 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B104B31	Key ,No signal	Passive/Sporadic
B104C29	Key ,Range/performance	Passive/Sporadic
U111400	Component protection ,GFA key	Passive/Sporadic
B18DEF0	Digital Key ,Invalid secret	Passive/Sporadic

19 - Gateway (4 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U111400	Component protection ,GFA key	Passive/Sporadic
U141100	Battery terminal recognition ,Open circuit	Passive/Sporadic
B1802F1	NV-Energy management ,Alarm triggered	Passive/Sporadic

44 - Power steering (4 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
U101400	Control module incorrectly coded	Active/static
U111800	Data set missg.	Active/static
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
B106513	Left rear bass speaker ,Open circuit	Active/static
B10CD00	Function restriction caused by energy management	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

76 - Parking aid (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

CA - Sunroof control module (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

Technician Notes

2017308858

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.