

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/all engine codes
VIN: AAVZZZAWZNU028131

Odometer Reading: 196687km
License Plate: HBZ487L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	 20
03 - Brakes 1	 2
08 - Air conditioning	 1
09 - Electronic central electric	 2
15 - Airbag	 1
17 - Instrument cluster	 3
19 - Gateway	 3
44 - Power steering	 1
5F - Information electronics 1	 4
76 - Parking aid	 3

DTC (40)

01 - Engine Control Module 1 (20 DTCs)

DTC	Description	Status
P051200	Starter Request Circuit	Passive/Sporadic
P06E900	Engine Starter Performance	Passive/Sporadic
P045800	Evaporative Emission (EVAP) system purge control valve A circuit short	Passive/Sporadic
P044400	Evaporative Emission (EVAP) system purge control valve A circuit open	Passive/Sporadic
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
P06EF00	Engine Restart Performance	Passive/Sporadic

U100800	Data bus diagnostic interface Check event memory	Passive/Sporadic
P086B00	Neutral Position Sensor 'A' Range/Performance	Passive/Sporadic
U042200	Invalid data received from body control unit	Passive/Sporadic
U015500	Lost communication with instrument cluster control unit	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Active/static
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P014100	O2 Sensor Heater Circ.,Bank1-Sensor2 Malfunction	Passive/Sporadic
P030000	Random Misfire Detected No Sub Type Information	Passive/Sporadic
P030100	Cylinder 1 Misfire Detected No Sub Type Information	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Passive/Sporadic
P014800	Fuel Delivery Error	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic
P042000	Catalyst System Efficiency Below Threshold Bank 1 No Sub Type Information	Active/static

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
C106A16	ABS valves voltage supply Voltage too low	Passive/Sporadic

08 - Air conditioning (1 DTC)

DTC	Description	Status
B10F000	Function restriction caused by compressor shut-off by engine	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B147918	Remote control vehicle key 1 Insufficient current	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

17 - Instrument cluster (3 DTCs)

DTC	Description	Status
B201000	No basic setting	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic
U111000	Function restriction due to communication interruption	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
U141100	Battery terminal recognition Open circuit	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (4 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U111100	Function restriction caused by missing message	Active/static
U111100	Function restriction caused by missing message	Passive/Sporadic
U11B800	Interface for external media No communication	Passive/Sporadic

76 - Parking aid (3 DTCs)

DTC	Description	Status
B10F714	Left front park assist sensor Open circuit/short circuit to ground	Active/static
B10F731	Left front parking aid sensor No signal	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic

Technician Notes

2017302498

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.