Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVTFR87JPD162724

Odometer Reading: 28171
License Plate: LX59SMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V5.70

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
TCM(Transmission Control Module)	0
ABS(Anti-lock Brake System)	2
SRS(Supplemental Restraint System)	0
IBS(Intelligent Battery System)	0
PAS(Parking Aid System) ADAS	3
BCM(Body Control Module)	2
NCU(Navigation Center Unit)	0
WAM(Wireless Access Module)	0

DTC (7)

ABS(Anti-lock Brake System) (2 DTCs)

DTC	Description	Status
U0136_87	Lost communication with DLC	Not present
U1840_86	Invalid data received from BCM (stop lamp)	Not present

PAS(Parking Aid System) (3 DTCs)

DTC	Description	Status
U0100_00	Lost communication with ECM or PCM	Not present
U0101_00	Lost communication with TCM	Not present
U0155_00	Lost communication with instrument panel cluster (IPC) control module	Not present

BCM(Body Control Module) (2 DTCs)

DTC	Description	Status
C172D_12	Left tail lamp output circuit short to battery	Not present
C0023_12	Stop lamp output circuit short to battery	Not present

Technician Notes
2018313361

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.