

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Ranger / Mazda B-Series / Troller/--
VIN: AFAPXXMJ2PKJ56121

Odometer Reading: 154671
License Plate: DH32XXZN

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (16)

System	Status/DTC
PCM(Powertrain control module)	 0
TCM(Transmission control module)	 0
ABS(Anti-lock brake system)	 0
RCM(Restraint control module)	 0
IPC(Instrument panel control module)	 1
ACM(Audio control module)	 0
APIM(Accessory protocol interface module)	 0
BdyCM(Body control module)	  6
FCDIM(Front control/display interface module)	 0
FCIM(Front controls interface module)	 0
GWM(Gateway module A)	 0
PAM(Parking aid module)	  0
PSCM(Power steering control module)	 0
RTM(Radio transceiver module)	 0
SCCM(Steering column control module)	 0
TRM(Trailer module)	 0

DTC (7)

IPC(Instrument panel control module) (1 DTC)

DTC	Description	Status
U0100:00-08	Lost Communication With ECM(Electronic Control Module)/PCM(Powertrain Control Module) A	CMDTCs

BdyCM(Body control module) (6 DTCs)

DTC	Description	Status
B115E:08-08	Camera Module	CMDTCs
B124B:15-08	Left Daytime Running Light	CMDTCs
B12C2:15-0A	Puddle Lamp	CMDTCs
B1313:15-0A	Interior Lighting Output	CMDTCs
B1D01:15-48	Right Low Beam	CMDTCs
B1D02:15-48	Left High Beam Circuit	CMDTCs

Technician Notes

2017303126

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.