Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261023093514
Test Time: 2026-10-23 09:35:14
Technician: Werner

BAICMotor VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BAICMotor/BAICMotor/SUV/RUBIK/ Mofang/ X55/ BAIC X55/ Beijing 5/ Tiger Six / Cirelli 4/--

Odometer Reading: 43258

VIN: AFDMCUAK1RA000105

License Plate: LCT034MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V12.00

Repair Order Number: --

System Scanned (1)

System	Status/DTC
SRS (Supplementary Restraint System)	0

DTC (0)

Technician Notes

2017316339

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.