Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20260930154302
Test Time: 2026-09-30 15:43:02
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTAA3DD501735232
Odometer Reading: 37952km
License Plate: HHP856L

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (18)

System		Status/DTC
Brake		3
SRS airbag		0
Combination meter		2
Pre-Collision system	ADAS	2
Air conditioner		1
Front radar sensor	ADAS	0
Navigation system		2
Starting control		0
Power source control		1
Entry&Start		1
Headlamp auto leveling	ADAS	1
Clearance sonar	ADAS	3
Radar cruise 2	ADAS	0
4WD		0
PPS		1
Front recognition camera	ADAS	1
Central gateway		0
Lane control	ADAS	2

DTC (20)

Brake (3 DTCs)

DTC	Description	Status
C137BA2	Brake system control module "A" system voltage system voltage low	Confirmed
U010087	Lost communication with ECM/PCM 'A' missing message	Confirmed
U010187	Lost communication with transmission control module (TCM) missing message	Confirmed

Combination meter (2 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
B150A	Lost communication with HMI-LAN	History

Pre-Collision system (2 DTCs)

DTC	Description	Status
U023587	Lost communication with cruise control front distance range sensor single sensor or center missing message	Confirmed
U010087	Lost communication with ECM/PCM 'A' missing message	Confirmed

Air conditioner (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Navigation system (2 DTCs)

DTC	Description	Status
B15A0	Lane master fault	History
U0100	Engine/EV electronic control unit(ECU) communication	History

Power source control (1 DTC)

DTC	Description	Status
U0100	ECM/EV communication	History

Entry&Start (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Headlamp auto leveling (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Clearance sonar (3 DTCs)

DTC	Description	Status
C1AEC	Front sensor communication circuit	History
U0100	Lost communication with ECM/PCM 'A'	History

U0101	Lost communication with transmission control module (TCM)	History

PPS (1 DTC)

DTC	Description	Status
U010087	Lost communication with ECM/PCM 'A' missing message	Confirmed

Front recognition camera (1 DTC)

DTC	Description	Status
U010087	Lost communication with ECM/PCM 'A' missing message	Confirmed

Lane control (2 DTCs)

DTC	Description	Status
U010087	Lost communication with ECM/PCM 'A' missing message	Confirmed
U023587	Lost communication with cruise control front distance range sensor single sensor or center missing message	Confirmed

Technician Notes

2017034579

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.