Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTBA3CD206226370

Odometer Reading: 165617km
License Plate: KV68RYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System		Status/DTC
Engine and transmission		0
Brake		0
SRS airbag		0
Combination meter		1
Air conditioner		1
Navigation system		1
Headlamp auto leveling	ADAS	1
Clearance sonar	ADAS	3
Central gateway		0
Radar cruise 1	ADAS	0
PPS		0
4WD		0

DTC (7)

Combination meter (1 DTC)

DTC	Description	Status
B150A	Lost communication with HMI-LAN	History

Air conditioner (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Navigation system (1 DTC)

DTC	Description	Status
U0100	Engine/EV electronic control unit(ECU) communication	History

Headlamp auto leveling (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Clearance sonar (3 DTCs)

DTC	Description	Status
C1AEC	Front sensor communication circuit	History
U0100	Lost communication with ECM/PCM 'A'	History
U0101	Lost communication with transmission control module (TCM)	History

Technician Notes

2017310677

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.