

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--
VIN: AHTBF8JE901006814

Odometer Reading: 170898km
License Plate: KL39LHGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
Engine and ECT	 2
ABS/VSC/TRC	 5
SRS airbag	 0
Combination meter	 0
Main body	 3
Driver door motor	 0
Air conditioner	 1
EMPS	 0
Radar cruise 1	  0

DTC (11)

Engine and ECT (2 DTCs)

DTC	Description	Status
P1604	Startability fault	Current
P1604	Startability fault	History

ABS/VSC/TRC (5 DTCs)

DTC	Description	Status
U0123	Lost communication with yaw rate sensor (YRS) module	History
C1241	Low or high power supply voltage	History
U0100	Lost communication with ECM/PCM/EV "A"	History
C1332	Right rear speed sensor circuit open	History
C1445	Vehicle driven with steering angle sensor (SAS) not initialized	History

Main body (3 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
U0101	Lost communication with transmission control module (TCM)	History
U0151	Lost communication with restraints control module	History

Air conditioner (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Technician Notes

2017302496

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.