Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261022082026
Test Time: 2026-10-22 08:20:26
Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTCB8CB704165221

Odometer Reading: 11418km
License Plate: HRN431L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and transmission	0
ABS/VSC/TRC	1
SRS airbag	0
Combination meter	1
Radar cruise 1 ADAS	0

DTC (2)

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1425	Stop switch circuit open	Current

Combination meter (1 DTC)

DTC	Description	Status
U0129	Lost communication with brake system control module	History

Technician Notes

2017315634

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.