

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTEW6CB900998284

Odometer Reading: 211750km
License Plate: LCD541NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and ECT	 2
ABS/VSC/TRC	 2
SRS airbag	 1
Combination meter	 1
Radar cruise 1	  0

DTC (6)

Engine and ECT (2 DTCs)

DTC	Description	Status
P1604	Startability fault	Current
P1604	Startability fault	History

ABS/VSC/TRC (2 DTCs)

DTC	Description	Status
C1241	Low or high power supply voltage	Current
C1405	Right front speed sensor circuit open or short	Current

SRS airbag (1 DTC)

DTC	Description	Status
B1801	Driving side squib circuit open	History

Combination meter (1 DTC)

DTC	Description	Status
U0129	Lost communication with brake system control module	History

Technician Notes

2017301666

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.