

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTJB3DD704528644

Odometer Reading: 121037km
License Plate: LV21VCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
Engine and transmission	 0
Brake	 0
SRS airbag	 0
Combination meter	 1
Navigation system	 1
Clearance sonar	  3
Central gateway	 0
Radar cruise 1	  0
PPS	 0
4WD	 0

DTC (5)

Combination meter (1 DTC)

DTC	Description	Status
B150A	Lost communication with HMI-LAN	History

Navigation system (1 DTC)

DTC	Description	Status
U0100	Engine/EV electronic control unit(ECU) communication	History

Clearance sonar (3 DTCs)

DTC	Description	Status
C1AEC	Front sensor communication circuit	History
U0100	Lost communication with ECM/PCM 'A'	History

U0155

Lost communication with instrument panel cluster (IPC)
control module

History

Technician Notes
2017303410

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.