Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261028134840
Test Time: 2026-10-28 13:48:40
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTJB3DD804537904
Odometer Reading: 38772km
License Plate: DDT558NC

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
Brake	0
SRS airbag	0
Combination meter	1
Navigation system	1
Clearance sonar ADAS	2
Central gateway	0
PPS	0
4WD	0

DTC (4)

Combination meter (1 DTC)

DTC	Description	Status
B150A	Lost communication with HMI-LAN	History

Navigation system (1 DTC)

DTC	Description	Status
U0100	Engine/EV electronic control unit(ECU) communication	History

Clearance sonar (2 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM 'A'	History
U0101	Lost communication with transmission control module (TCM)	History

Technician Notes

2017318683

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.