

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--

VIN: AHTSS22P207151456

Odometer Reading: 62333km

License Plate: KYH098MP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V11.60

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (4)

System	Status/DTC
Engine and ECT	✓ 0
SRS airbag	✗ 3
Combination meter	✗ 3
Immobilizer	✓ 0



DTC (6)

SRS airbag (3 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History
B1906	Pretensioner squib (left) circuit open	History

Combination meter (3 DTCs)

DTC	Description	Status
U0129	Lost communication with brake system control module	Current
U0129	Lost communication with brake system control module	History
B1507	Turn signal circuit open	History

Technician Notes

2017165812

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.