

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P307146668

Odometer Reading: 314417km
License Plate: LD21KFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 3
SRS airbag	 2
Combination meter	 0
Immobilizer	 0

DTC (5)

ABS/VSC/TRC (3 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1241	Low or high power supply voltage	History
C1402	Fault in front speed sensor left circuit	History

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	Current
B1801	Driving side squib circuit open	History

Technician Notes

2017305252

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.