Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261013141828
Test Time: 2026-10-13 14:18:28
Technician: Andrick

Mazda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mazda/MAZDA3 / AXELA/--
VIN: JM6BN24Z5J0188397
Odometer Reading: 190435
License Plate: JTP238MP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
PCM(Powertrain control module)	0
ABS(Anti-lock brake system)	2
RCM(Restraint control module)	1
IC(Instrument cluster)	0
EPS(Electronic-controlled power steering)	0
CMU(Connectivity master unit)	4
F_BCM(Front body control module)	0
R_BCM(Rear body control module)	0
SSU(Start stop unit)	1

DTC (8)

ABS(Anti-lock brake system) (2 DTCs)

DTC	Description	Status
U0452:86-20	Invalid Data Received From Restraints Control Module	CMDTCs
U3003:16-68	Battery Voltage	CMDTCs

RCM(Restraint control module) (1 DTC)

DTC	Description	Status
U3003:16-08	Battery Voltage	CMDTCs

CMU(Connectivity master unit) (4 DTCs)

DTC	Description	Status
B1238:16-0A	Speaker Amplifier	CMDTCs
U0184:00-08	Lost Communication With Radio	CMDTCs
U0187:00-08	Lost Communication With Digital Disc Player/Changer Module A	CMDTCs

U3003:16-08	Battery Voltage	CMDTCs

SSU(Start stop unit) (1 DTC)

DTC	Description	Status
B13D3:16-08	PATS(Passive Anti Theft System) Transmitter	CMDTCs

Technician Notes

2017311535

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.