Mazda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mazda/CX-5/--
VIN: JM6KF2W7AK0308421

Odometer Reading: 486719
License Plate: (N > A)

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
TCM(Transmission control module)	0
ABS(Anti-lock brake system)	1
RCM(Restraint control module)	0
IC(Instrument cluster)	0
EPB(Electric parking brake)	1
EPS(Electronic-controlled power steering)	0
AFS/ALM(Adaptive front lighting system/auto leveling module) ADAS	0
CMU(Connectivity master unit)	1
EATC(Electronic air temperature controller)	0
F_BCM(Front body control module)	0
R_BCM(Rear body control module)	0
SSU(Start stop unit)	0
PCM(Powertrain control module)	3

DTC (6)

ABS(Anti-lock brake system) (1 DTC)

DTC	Description	Status
C0023:62-68	Stop Lamp Control	CMDTCs

EPB(Electric parking brake) (1 DTC)

DTC	Description	Status
C1020:68-08	Brake System Fill Not Complete	CMDTCs

CMU(Connectivity master unit) (1 DTC)

DTC	Description	Status
B1238:16-0A	Speaker Amplifier	CMDTCs

PCM(Powertrain control module) (3 DTCs)

DTC	Description	Status
P0014:00-28	Exhaust (B) Camshaft Position Timing - Over-Advanced (Bank 1)	CMDTCs
P0421:00-EC	Catalyst 1 Efficiency Below Threshold (Bank 1)	CMDTCs
P0524:00-AF	Engine Oil Pressure Too Low	CMDTCs

Technician Notes

2017317030

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.