Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261021144949
Test Time: 2026-10-21 14:49:49
Technician: Sbu

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/SX4/--
VIN: JSAGYB51S00302282

Odometer Reading: 228983
License Plate: KLR925MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	2
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	2
SRS(Airbag)	3
EPS(Power steering)	0
A/C(Air-Conditioning)	1
BCM(Body Control Module)	1
4WD(Four-Wheel Drive)	3
SMK(Immobilizer and/or keyless system)	2

DTC (14)

ECM/PCM(Engine/powertrain) (2 DTCs)

DTC	Description	Status
P0101	Mass or volume air flow A circuit range/performance	History
P0171	System too lean (bank 1)	Pending

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1091	CAN invalid data from ECM	History
C1075	Steering angle sensor calibration not completed	Current

SRS(Airbag) (3 DTCs)

DTC	Description	Status
B1084	Driver side impact sensor circuit open	History
B1094	Passenger side impact sensor circuit open	History
B1017	Power source voltage too low	History

A/C(Air-Conditioning) (1 DTC)

DTC	Description	Status
B1503	Evaporator temperature sensor circuit fault	History

BCM(Body Control Module) (1 DTC)

DTC	Description	Status
B1150	Airbag communication circuit fault	History

4WD(Four-Wheel Drive) (3 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM	History
U0121	Lost communication with ABS or electronic stability program control module	History
U0155	Lost communication with Instrument Panel Cluster (IPC) control module	History

SMK(Immobilizer and/or keyless system) (2 DTCs)

DTC	Description	Status
P0101	Mass or volume air flow A circuit range/performance	History
P0171	System too lean (bank 1)	Pending

Technician Notes

2017315452

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.