Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Baleno/--
VIN: JTDGWC52S00767776

Odometer Reading: 137402
License Plate: KG73GFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	5
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	1
CGW(Central gateway control module)	1
EPS(Power steering)	0
BCM(Body Control Module)	2
SMK(Immobilizer and/or keyless system)	2

DTC (11)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (5 DTCs)

DTC	Description	Status
C1057	Power supply voltage	History
C1023	Yaw Rate Sensor (YRS) circuit performance	History
U0100	Lost communication with ECM	History
U0126	Lost communication with steering angle sensor module	History
C1091	CAN invalid data from ECM	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM	History

CGW(Central gateway control module) (1 DTC)

DTC	Description	Status
U0100-87	Lost communication with ECM	History

BCM(Body Control Module) (2 DTCs)

DTC	Description	Status
B1189	Immobilizer antenna communication fault	History
U0100	Lost communication with ECM	History

SMK(Immobilizer and/or keyless system) (2 DTCs)

DTC	Description	Status
B1189	Immobilizer antenna communication fault	History
U0100	Lost communication with ECM	History

Technician Notes

2017317360

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.