Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261014113403
Test Time: 2026-10-14 11:34:03
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Starlet/--
VIN: JTDJWCA3S00545170

Odometer Reading: 70578
License Plate: MD96WKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
TCM(Transmission Control Module)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	3
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	0
CGW(Central gateway control module)	0
EPS(Power steering)	0
BCM(Body Control Module)	1

DTC (4)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (3 DTCs)

DTC	Description	Status
C1157-1C	Power supply voltage abnormal	History
C1161-07	Pump motor circuit	History
U0402-81	CAN invalid data from Transmission Control Module (TCM)	History

BCM(Body Control Module) (1 DTC)

DTC	Description	Status
B150A-13	Sunload Sensor Circuit Open	Current

Technician Notes

2017311879

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.