

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: JTFPA9AP008026523

Odometer Reading: 121040km
License Plate: LGK836MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (11)

System	Status/DTC
Engine and transmission	✓ 0
Brake/EPB	✗ 1
SRS airbag	✓ 0
Combination meter	✓ 0
Main body	✗ 1
Driver door motor	✗ 2
Master switch	✓ 0
Passenger door motor	✓ 0
Air conditioner	✓ 0
Central gateway	✓ 0
Steering angle sensor (SAS)	✓ 0



DTC (4)

Brake/EPB (1 DTC)

DTC	Description	Status
C137BA2	Brake system control module "A" system voltage system voltage low	Confirmed

Main body (1 DTC)

DTC	Description	Status
U0163	Lost communication with navigation control module	History

Driver door motor (2 DTCs)

DTC	Description	Status
B2311	Motor fault	History

B2312

Master switch of driver side door fault

History

Technician Notes
2017302481

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.