Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261026144709
Test Time: 2026-10-26 14:47:09
Technician: Werner

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Accent(RB)/--
VIN: KMHCT41DLKU480774

Odometer Reading: 561577
License Plate: JN07ZYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	2
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
BCM (Body Control)	0

DTC (2)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102	Battery voltage low	History
B1346	Driver airbag (DAB) resistance too high (1st Stage)	Active

Technician Notes

2017317189

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.