Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Accent(RB)/--
VIN: KMHCT41DLKU481067

Odometer Reading: 253880
License Plate: NO plate n

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
ENG (Engine)	4
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	3
AB (Airbag)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
BCM (Body Control)	0

DTC (7)

ENG (Engine) (4 DTCs)

DTC	Description	Status
P0011	Intake camshaft position (CMP) A timing over-Advanced or system performance (Bank 1)	Pending
P0271	Cylinder 4 injector circuit high	Active
P0326	Knock sensor 1 circuit range/Performance (Bank 1)	Active
P0620	Alternator control circuit	History

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (3 DTCs)

DTC	Description	Status
C1201	Left front vehicle speed sensor (VSS) range/performance/Intermittent	History
C1203	Right front vehicle speed sensor (VSS) circuit open or short	Active
C1206	Left rear wheel speed sensor (WSS) circuit open or short	History

Technician Notes

2017316404

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.