

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Tucson(TL)/--
VIN: KMHJ381AMHU369887

Odometer Reading: 151224
License Plate: JX10KKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
A/C (Air Conditioner)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
SMK (Smart Key Unit)	 0
SJB (Smart Junction Block)	 0
BSD-L (Blind Spot Detection-L)	  0
BSD-R (Blind Spot Detection-R)	  0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1651:00	Crash recorded in driver side airbag (Replace SRSCM)	Active

Technician Notes

2017304825

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.