Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261027122446
Test Time: 2026-10-27 12:24:46
Technician: Barney

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Picanto/Morning (JA)/--
VIN: KNAB2511LKT373931
Odometer Reading: 120332
License Plate: HV35FGGP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	0
AB (Airbag)	1
CLU (Cluster Module)	0
A/C (Air Conditioner)	0
EPS (Motor Driven Power Steering)	1
IMMO (Immobilizer)	0

DTC (2)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes

2017317768

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.