Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261027144745
Test Time: 2026-10-27 14:47:45
Technician: Itu

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Picanto/--
VIN: KNAB2511LST373719

Odometer Reading: 8895KM
License Plate: MK59LGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	2
CLU (Cluster Module)	0
I-TPMS (I-Tire Pressure Monitoring System)	0
A/C (Air Conditioner)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	0
ICU (Integrated Central Control Unit)	0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	0
RVM (Rear View Monitor) ADAS	0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	0

DTC (2)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B2615:00	Airbag control unit (ACU) & cluster airbag lamp CAN message mismatch	History
B2617:00	Cluster airbag warning lamp CAN message timeout	History

Technician Notes

2017318019

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.