Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Forte/Koup(TD)/--
VIN: KNAFW612LC5571267

Odometer Reading: 201773
License Plate: BY92CKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ENG (Engine)	0
ABS (Anti Lock Brake)	5
AB (Airbag)	2
A/C (Air Conditioner)	0
EPS (Motor Driven Power Steering)	1
BCM (Body Control)	0
CODE (Transmitter Code Saving)	0
IMMO (Immobilizer)	0

DTC (8)

ABS (Anti Lock Brake) (5 DTCs)

DTC	Description	Status
C1200	Left front vehicle speed sensor (VSS) circuit open or short	History
C1611	CAN Timeout - Engine management system (EMS)	History
C1612	CAN Timeout - TCM	History
C1616	CAN Bus off	History
C1623	CAN Timeout - Steering angle sensor (SAS)	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102	Battery voltage low	History
B1334	Passenger front impact sensor (FIS) communication error	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1611	CAN Timeout - Engine management system (EMS)	History

Technician Notes
2017315661

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.