HAVAL VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/HAVAL/Haval H2/2019 (China 6)/--
VIN: LGWEE4A45MH907261

Odometer Reading: 109274
License Plate: LD78CKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
ECM (Engine Control Module)	1
ESP (Electronic Stability Program)	1
SRS (Supplemental Restraint System)	2
BCM (Body Control Module)	11
ICM/IP (Instrument Cluster Module/Instrument Pannel)	0
A/C (Air Conditioning) -A/C (Air Conditioning) - Red Logo	0
PEPS (Passive Start System)	2
GW (Gateway)-Gateway - Continental	0
ESCL (Electronic Steering Column Lock)	4
EPS (Electric Power Steering)-EPS (Electric Power Steering)	2
SAS (Steering Angle Sensor)	0
CMS (CAN Signal Conversion System)	0

DTC (23)

ECM (Engine Control Module) (1 DTC)

DTC	Description	Status
P147900	Please refer to vehicle service manual.	History DTC

ESP (Electronic Stability Program) (1 DTC)

DTC	Description	Status
C102312	APB key loop fault	Current DTC

SRS (Supplemental Restraint System) (2 DTCs)

DTC	Description	Status
B103414	Crash Output of Controller Short to GND or Open	History DTC
U110116	Power supply voltage too low	History DTC

BCM (Body Control Module) (11 DTCs)

DTC	Description	Status
B141313	Left brake lamp circuit open	Current DTC
B141613	Right brake lamp circuit open	Current DTC
B142013	Trailer brake light open circuit	Current DTC
B145013	Trailer reversing light open circuit	Current DTC
B14DA96	Left front wheel transmitter lost	Current DTC
B14DB96	Right front wheel transmitter lost	Current DTC
B14DC96	Left rear wheel transmitter lost	Current DTC
B14DD96	Right rear wheel transmitter lost	Current DTC
B140518	Right turn signal light: one bulb open circuit	History DTC
B140918	Left turn signal light: one bulb open circuit	History DTC
B145A13	Trailer rear fog light open circuit or short to ground	History DTC

PEPS (Passive Start System) (2 DTCs)

DTC	Description	Status
B140615	Keyless entry antenna 1 short to power or open circuit	Current DTC
B140C13	Driver area door handle sensor open circuit	Current DTC

ESCL (Electronic Steering Column Lock) (4 DTCs)

DTC	Description	Status
U110016	Voltage too low	History DTC
U100587	NMLimphome	History DTC
B150105	Engine speed data limit exceeded	History DTC
B150104	Front wheel speed data limit exceeded	History DTC

EPS (Electric Power Steering)-EPS (Electric Power Steering) (2 DTCs)

DTC	Description	Status
C100200	Supply voltage below alert value	History DTC
C100400	Supply voltage below hazard value	History DTC

Technician Notes

2017307849

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.