

# HAVAL VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/HAVAL/Haval H6/China/H6S (hybrid edition)/--  
VIN: LGWFF6A56SH932527

Odometer Reading: 37434  
License Plate: MF27FPGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V11.00

Serial Number: VB8GJCC01509  
Repair Order Number: --



## System Scanned ( 26 )

| System                                                                              | Status/DTC |
|-------------------------------------------------------------------------------------|------------|
| ECM (Engine Control Module)                                                         | ✓ 0        |
| ESP (Electronic Stability Program)                                                  | ✓ 0        |
| SRS (Supplemental Restraint System)                                                 | ✗ 1        |
| BCM (Body Control Module)-BCM (Body Control Module) - KOSTAL                        | ✓ 0        |
| TPMS (Tire Pressure Monitoring System)                                              | ✗ 2        |
| A/C (Air Conditioning) -A/C (Air Conditioning) - MIND                               | ✗ 8        |
| IPAS (Integrated Parking Assist System)                                             | ADAS ✗ 1   |
| CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function | ✓ 0        |
| DDCM (Driver Door Control Module)                                                   | ✗ 1        |
| EPS (Electric Power Steering)-EPS (Electric Power Steering) - ZF                    | ✓ 0        |
| F-PBOX (Front Fuse Box Module)                                                      | ✗ 1        |
| GW (Gateway)-GW (Gateway) - Aptiv                                                   | ✓ 0        |
| HAP (High-level Automatic Parking)                                                  | ADAS ✗ 1   |
| HUD (Head-Up Display)-HUD (Head-Up Display) - E-lead                                | ADAS ✓ 0   |
| HUT (Multimedia Player Assembly)                                                    | ADAS ✓ 0   |
| SHM (Seat Heating Module)-HVSM (Heating and Ventilation Seat Module) - Gentherm     | ✓ 0        |
| IFC (Intelligent Front Camera)                                                      | ADAS ✗ 2   |

|                                                                |      |                                                                                       |
|----------------------------------------------------------------|------|---------------------------------------------------------------------------------------|
| PAS (Parking Assist System)                                    | ADAS |  1 |
| PDCM (Passenger Door Control Module)                           |      |  1 |
| PLG (Power Liftgate)                                           |      |  0 |
| R-PBOX (Rear Fuse Box Module)                                  |      |  1 |
| RSDS-L (Radar Sensing and Detection System - Left)             | ADAS |  3 |
| RSDS-R (Radar Sensing and Detection System - Right)            | ADAS |  3 |
| SBWM (Shift-By-Wire Module)-SBWM (Shift-By-Wire Module) - MIND |      |  0 |
| T-Box (Telematics Box)-T-Box (Telematics Box) - Lear           |      |  0 |
| WPC (Wireless Power Charging)                                  |      |  0 |

 **DTC ( 26 )****SRS (Supplemental Restraint System) ( 1 DTC )**

| DTC     | Description                | Status      |
|---------|----------------------------|-------------|
| U110116 | Diagnostic voltage too low | History DTC |

**TPMS (Tire Pressure Monitoring System) ( 2 DTCs )**

| DTC     | Description                                          | Status      |
|---------|------------------------------------------------------|-------------|
| C007704 | Left rear tire low pressure warning                  | Current DTC |
| U016387 | Lost communication with HUT (navigation host system) | History DTC |

**A/C (Air Conditioning) -A/C (Air Conditioning) - MIND ( 8 DTCs )**

| DTC     | Description                                                | Status      |
|---------|------------------------------------------------------------|-------------|
| U024587 | Lost communication with navigation host system             | History DTC |
| U110116 | Voltage too low                                            | History DTC |
| B140915 | Interior temperature sensor circuit open or short to power | History DTC |
| U014687 | Lost communication with gateway                            | History DTC |
| U110887 | Lost communication with Front Fuse Box Module (F-PBox)     | History DTC |
| U100287 | Lost communication with Passive Entry Passive Start (PEPS) | History DTC |
| U110687 | Lost communication with combination switch assembly        | History DTC |
| U012287 | Lost communication with electronic stability program-ABS   | History DTC |

**IPAS (Integrated Parking Assist System) ( 1 DTC )**

| DTC     | Description                                  | Status      |
|---------|----------------------------------------------|-------------|
| U100087 | Lost communication with Air Bag Module (ABM) | History DTC |

**DDCM (Driver Door Control Module) ( 1 DTC )**

| DTC     | Description                                                   | Status      |
|---------|---------------------------------------------------------------|-------------|
| U010187 | Lost communication with Transmission Control Unit (TCU)_PTCAN | History DTC |

**F-PBOX (Front Fuse Box Module) ( 1 DTC )**

| DTC     | Description                                          | Status      |
|---------|------------------------------------------------------|-------------|
| U024587 | Lost communication with navigation host system (HUT) | History DTC |

**HAP (High-level Automatic Parking) ( 1 DTC )**

| DTC     | Description                                  | Status      |
|---------|----------------------------------------------|-------------|
| U100087 | Lost communication with Air Bag Module (ABM) | History DTC |

**IFC (Intelligent Front Camera) ( 2 DTCs )**

| DTC     | Description       | Status      |
|---------|-------------------|-------------|
| C152000 | Internal error    | History DTC |
| C153700 | Windshild blurred | History DTC |

**PAS (Parking Assist System) ( 1 DTC )**

| DTC     | Description                                | Status      |
|---------|--------------------------------------------|-------------|
| U100087 | Lost communication with Air Bag Module ABM | History DTC |

**PDCM (Passenger Door Control Module) ( 1 DTC )**

| DTC     | Description                                                   | Status      |
|---------|---------------------------------------------------------------|-------------|
| U010187 | Lost communication with Transmission Control Unit (TCU)_PTCAN | History DTC |

**R-PBOX (Rear Fuse Box Module) ( 1 DTC )**

| DTC     | Description                                          | Status      |
|---------|------------------------------------------------------|-------------|
| U024587 | Lost communication with navigation host system (HUT) | History DTC |

**RSDS-L (Radar Sensing and Detection System - Left) ( 3 DTCs )**

| DTC     | Description                                           | Status      |
|---------|-------------------------------------------------------|-------------|
| U014087 | Lost communication with KBCM                          | History DTC |
| U019987 | Lost communication with driver door control module    | History DTC |
| U020087 | Lost communication with passenger door control module | History DTC |

**RSDS-R (Radar Sensing and Detection System - Right) ( 3 DTCs )**

| DTC     | Description                                           | Status      |
|---------|-------------------------------------------------------|-------------|
| U014087 | Lost communication with KBCM                          | History DTC |
| U019987 | Lost communication with driver door control module    | History DTC |
| U020087 | Lost communication with passenger door control module | History DTC |

**Technician Notes**  
2017305017

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.