Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261013115227
Test Time: 2026-10-13 11:52:27
Technician: Sbu

HAVAL VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/HAVAL/Haval H6/China/H6S (hybrid edition)/--
VIN: LGWFF6A57NH932637

Odometer Reading: 72991
License Plate: KT56CTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (20)

System		Status/DTC
ECM (Engine Control Module)		0
ESP (Electronic Stability Program)		0
SRS (Supplemental Restraint System)		1
BCM (Body Control Module)-BCM (Body Control Module) - KOSTAL		3
TPMS (Tire Pressure Monitoring System)		1
A/C (Air Conditioning) -A/C (Air Conditioning) - MIND		5
IPAS (Integrated Parking Assist System)	ADAS	1
CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function		0
DDCM (Driver Door Control Module)		3
EPS (Electric Power Steering)-EPS (Electric Power Steering) - ZF		0
F-PBOX (Front Fuse Box Module)		2
GW (Gateway)-GW (Gateway) - Aptiv		6
HAP (High-level Automatic Parking)	ADAS	1
HUT (Multimedia Player Assembly)	ADAS	5
IFC (Intelligent Front Camera)	ADAS	5
PAS (Parking Assist System)	ADAS	1
PDCM (Passenger Door Control Module)		3
R-PBOX (Rear Fuse Box Module)		3

SBWM (Shift-By-Wire Module)-SBWM (Shift-By-Wire Module) - MIND	0
T-Box (Telematics Box)-T-Box (Telematics Box) - Lear	0

DTC (40)

SRS (Supplemental Restraint System) (1 DTC)

DTC	Description	Status
U110116	Diagnostic voltage too low	History DTC

BCM (Body Control Module)-BCM (Body Control Module) - KOSTAL (3 DTCs)

DTC	Description	Status
B185100	Key battery low	Current DTC
U014400	Sunroof monitoring fault	History DTC
U110987	Lost communication with R-PBOX	History DTC

TPMS (Tire Pressure Monitoring System) (1 DTC)

DTC	Description	Status
C007703	Right rear tire low pressure warning	History DTC

A/C (Air Conditioning) -A/C (Air Conditioning) - MIND (5 DTCs)

DTC	Description	Status
U024587	Lost communication with navigation host system	History DTC
U012287	Lost communication with electronic stability program-ABS	History DTC
U110116	Voltage too low	History DTC
U110017	Voltage too high	History DTC
B141511	Stepper motor 12V power supply circuit short to ground	History DTC

IPAS (Integrated Parking Assist System) (1 DTC)

DTC	Description	Status
U100087	Lost communication with Air Bag Module (ABM)	History DTC

DDCM (Driver Door Control Module) (3 DTCs)

DTC	Description	Status
U012287	Lost communication with ESP(ABS)	History DTC
U010187	Lost communication with Transmission Control Unit (TCU)_PTCAN	History DTC
U024587	Lost communication with navigation host system (HUT)	History DTC

F-PBOX (Front Fuse Box Module) (2 DTCs)

DTC	Description	Status
U010087	Lost communication with ECM	History DTC

U012287	Lost communication with ESP (electronic stability program)	History DTC

GW (Gateway)-GW (Gateway) - Aptiv (6 DTCs)

DTC	Description	Status
U100A63	SecOC key service time long	Current DTC
U010087	Lost communication with ECM	History DTC
U100087	Lost communication with Air Bag Module (ABM)	History DTC
U014387	Lost Communication with IFC	History DTC
U013187	Lost communication with Electric Power Steering (EPS)	History DTC
U010187	TCU (DTC) lost communication	History DTC

HAP (High-level Automatic Parking) (1 DTC)

DTC	Description	Status
U100087	Lost communication with Air Bag Module (ABM)	History DTC

HUT (Multimedia Player Assembly) (5 DTCs)

DTC	Description	Status
B13F513	Microphone #1 circuit open	History DTC
B1A1013	FM1 antenna circuit open	History DTC
U010087	Lost communication with ECM	History DTC
U010187	Lost communication with Transmission Control Unit (TCU)	History DTC
U014387	Lost communication with Intelligent Front Camera (IFC)	History DTC

IFC (Intelligent Front Camera) (5 DTCs)

DTC	Description	Status
C152000	Internal error	History DTC
U024587	Lost communication with navigation host system (HUT)	History DTC
U121881	Driving multi-mode signal abnormal	History DTC
C153600	Ambient interference	History DTC
U015587	Lost communication with HUT (IP)	History DTC

PAS (Parking Assist System) (1 DTC)

DTC	Description	Status
U100087	Lost communication with Air Bag Module ABM	History DTC

PDCM (Passenger Door Control Module) (3 DTCs)

DTC	Description	Status
U012287	Lost communication with ESP(ABS)	History DTC
U010187	Lost communication with Transmission Control Unit (TCU)_PTCAN	History DTC
U024587	Lost communication with navigation host system (HUT)	History DTC

R-PBOX (Rear Fuse Box Module) (3 DTCs)

DTC	Description	Status
U010087	Lost communication with ECM	History DTC
U012287	Lost communication with ESP (electronic stability program)	History DTC
U010187	Lost communication with transmission control unit (TCU)	History DTC

Technician Notes

2017311205

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.