

HAVAL VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/HAVAL/Haval H6/China/H6S (hybrid edition)/--
VIN: LGWFF6A58RH931650

Odometer Reading: 13442
License Plate: LBT388NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.00

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (26)

System	Status/DTC
ECM (Engine Control Module)	1
ESP (Electronic Stability Program)	0
SRS (Supplemental Restraint System)	0
BCM (Body Control Module)-BCM (Body Control Module) - KOSTAL	0
TPMS (Tire Pressure Monitoring System)	0
A/C (Air Conditioning) -A/C (Air Conditioning) - MIND	8
IPAS (Integrated Parking Assist System)	4
CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function	0
DDCM (Driver Door Control Module)	1
EPS (Electric Power Steering)-EPS (Electric Power Steering) - ZF	0
F-PBOX (Front Fuse Box Module)	1
GW (Gateway)-GW (Gateway) - Aptiv	1
HAP (High-level Automatic Parking)	4
HUD (Head-Up Display)-HUD (Head-Up Display) - E-lead	0
HUT (Multimedia Player Assembly)	1
SHM (Seat Heating Module)-HVSM (Heating and Ventilation Seat Module) - Gentherm	0
IFC (Intelligent Front Camera)	8

PAS (Parking Assist System)	ADAS	 4
PDCM (Passenger Door Control Module)		 1
PLG (Power Liftgate)		 1
R-PBOX (Rear Fuse Box Module)		 1
RSDS-L (Radar Sensing and Detection System - Left)	ADAS	 3
RSDS-R (Radar Sensing and Detection System - Right)	ADAS	 4
SBWM (Shift-By-Wire Module)-SBWM (Shift-By-Wire Module) - MIND		 0
T-Box (Telematics Box)-T-Box (Telematics Box) - Lear		 0
WPC (Wireless Power Charging)		 0

 DTC (43)**ECM (Engine Control Module) (1 DTC)**

DTC	Description	Status
U015587	ECU lost communication with instrument panel (IP) module	History DTC

A/C (Air Conditioning) -A/C (Air Conditioning) - MIND (8 DTCs)

DTC	Description	Status
U024587	Lost communication with navigation host system	History DTC
B140915	Interior temperature sensor circuit open or short to power	History DTC
U014687	Lost communication with gateway	History DTC
U110887	Lost communication with Front Fuse Box Module (F-PBox)	History DTC
U100287	Lost communication with Passive Entry Passive Start (PEPS)	History DTC
U110687	Lost communication with combination switch assembly	History DTC
U012287	Lost communication with electronic stability program-ABS	History DTC
U010087	Lost communication with ECM	History DTC

IPAS (Integrated Parking Assist System) (4 DTCs)

DTC	Description	Status
B110214	Rear camera voltage circuit open or short to power	Current DTC
U100087	Lost communication with Air Bag Module (ABM)	History DTC
B150202	Around view image and HUT connection error	History DTC
U018782	HUT32 rolling code error	History DTC

DDCM (Driver Door Control Module) (1 DTC)

DTC	Description	Status
-----	-------------	--------

U024587	Lost communication with navigation host system (HUT)	History DTC
---------	--	-------------

F-PBOX (Front Fuse Box Module) (1 DTC)

DTC	Description	Status
U024587	Lost communication with navigation host system (HUT)	History DTC

GW (Gateway)-GW (Gateway) - Aptiv (1 DTC)

DTC	Description	Status
U014387	Lost Communication with IFC	History DTC

HAP (High-level Automatic Parking) (4 DTCs)

DTC	Description	Status
B110214	Rear camera voltage circuit open or short to power	Current DTC
U100087	Lost communication with Air Bag Module (ABM)	History DTC
B150202	Around view image and HUT connection error	History DTC
U018782	HUT32 rolling code error	History DTC

HUT (Multimedia Player Assembly) (1 DTC)

DTC	Description	Status
B210149	Instrument panel display IC failure	History DTC

IFC (Intelligent Front Camera) (8 DTCs)

DTC	Description	Status
U024587	Lost communication with navigation host system (HUT)	History DTC
U121881	Driving multi-mode signal abnormal	History DTC
U124381	HUT (IP) error	History DTC
U124481	RSDS left target signal abnormal	History DTC
U124581	RSDS right target signal abnormal	History DTC
C153700	Windshild blurred	History DTC
C153600	Ambient interference	History DTC
U015587	Lost communication with HUT (IP)	History DTC

PAS (Parking Assist System) (4 DTCs)

DTC	Description	Status
B110214	Rear camera voltage circuit open or short to power	Current DTC
U100087	Lost communication with Air Bag Module ABM	History DTC
B150202	Faulty connection between surround view image and HUT	History DTC
U018782	HUT32 rolling code error	History DTC

PDCM (Passenger Door Control Module) (1 DTC)

DTC	Description	Status
U024587	Lost communication with navigation host system (HUT)	History DTC

PLG (Power Liftgate) (1 DTC)

DTC	Description	Status
U016387	Please refer to vehicle service manual.	History DTC

R-PBOX (Rear Fuse Box Module) (1 DTC)

DTC	Description	Status
U024587	Lost communication with navigation host system (HUT)	History DTC

RSDS-L (Radar Sensing and Detection System - Left) (3 DTCs)

DTC	Description	Status
U014087	Lost communication with KBCM	History DTC
U019987	Lost communication with driver door control module	History DTC
U020087	Lost communication with passenger door control module	History DTC

RSDS-R (Radar Sensing and Detection System - Right) (4 DTCs)

DTC	Description	Status
U014087	Lost communication with KBCM	History DTC
U019987	Lost communication with driver door control module	History DTC
U020087	Lost communication with passenger door control module	History DTC
C10A278	RSDS calibration deviation too large	History DTC

Technician Notes
2017305276

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.