Chery VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Chery/Tiggo series/Tiggo 5x/Tiggo 4/Tiggo 4 Pro/Tiggo Cross/Tiggo 5x/DR 4.0/DR 5.0/Sportequipe 5/MVM X55/MVM X55 Pro/--

Odometer Reading: 38363

VIN: LVVDB11B9RC111357

License Plate: MF89YZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V14.60

Repair Order Number: --

System Scanned (15)

System	Status/DTC
ECM (Engine system)	0
SRS (Supplementary Restraint System)-SRS-AIR BAG	0
IC (Instrument Cluster)-Combination instrument system	0
Tire Pressure Monitoring System (TPMS)-TPMS (Tire Pressure Monitoring System)	2
BCM (Body control system)-BDM (Body Domain Module)	2
AC (Automatic air conditioning system)	0
PEPS (Keyless start system)-PEPS	2
ABS (Anti-lock Brake System)/ESP (Electronic Stability Program)	0
EPS (Electronic Power Steering System)	0
IMMO (Immobilizer)-IMMO (engine immobilizer)	2
PAC (Parking Assist Control) ADAS	0
DVD (Audio Entertainment System)	0
SAS (Steering Angle System)	0
ESCL (Electronic Steering Column Lock)	0
CGW (Central Gateway)	0

DTC (8)

Tire Pressure Monitoring System (TPMS)-TPMS (Tire Pressure Monitoring System) (2 DTCs)

DTC	Description	Status
B103713	Please refer to vehicle service manual.	Current
B103813	Please refer to vehicle service manual.	Current

BCM (Body control system)-BDM (Body Domain Module) (2 DTCs)

DTC	Description	Status
B152E1D	Boot detection failed	Historic Fault Code
B150C00	Abnormal clutch pedal switch	Historic Fault Code

PEPS (Keyless start system)-PEPS (2 DTCs)

DTC	Description	Status
B152E1D	Starting failed	History
B150C00	Clutch Switch Signal Error	No sub-type/History

IMMO (Immobilizer)-IMMO (engine immobilizer) (2 DTCs)

DTC	Description	Status
B152E	Ignition switch start fault	Historic Fault Code
B150C	Clutch switch signal error	Historic Fault Code

Technician Notes

2017315644

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.