Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261021095736
Test Time: 2026-10-21 09:57:36
Technician: Werner

Mahindra VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mahindra/Xuv700/--
VIN: MA1NF2ZFFP6B78473
Odometer Reading: 53031
License Plate: LR83GRGP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V3.10
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
Engine management system (gasoline)	0
Mahindra body function module	4
Electronic temperature control	1
Electronic stability program	4
Silver_box	10
Immobiliser	6
Supplementary restraint system	5
Electronic power steering	0
Main gateway module	12
Transmission control unit	3
Head light control unit_1l	2
Head light control unit_2r	1

DTC (48)

Mahindra body function module (4 DTCs)

DTC	Description	Status
B110016	ECU undervoltage	Other
B115429	Invalid crash Input from Airbag ECU	Other
U181000	Left Head Light Control Unit (HLCU) 1 bus integrity check failed	Other
U181100	Right Head Light Control Unit (HLCU) 2 bus integrity check failed	Other

Electronic temperature control (1 DTC)

DTC	Description	Status
B134816	ECU undervoltage	Other

Electronic stability program (4 DTCs)

DTC	Description	Status
C002016	Return Flow Pump Supply Error	Other
C114446	Under voltage error	Other
U110500	Silver box node absent	Other
U30001C	Valve or Valve relay Supply Fault	Other

Silver_box (10 DTCs)

DTC	Description	Status
B202416	Silver box undervoltage	Other
B202347	Watchdog reset in Vehicle Interface Processor (VIP)	Other
B102504	Navigation/ map data corrupted	Current
B146D52	E-SIM not functioned (provisioning not completed)	Current
B147255	End Of Line (EOL) provisioning not completed	Current
B147542	Modem fault	Current
B147616	LTE antenna circuit short to ground	Other
B147C00	Passive Keyless Entry (PKE) ECU: IDs not programmed	Current
B148600	IPCL fault	Current
U103000	PKE message timeout	Current

Immobiliser (6 DTCs)

DTC	Description	Status
B2F4000	Transponder missing/no response	Other
B2F4100	Tag auth failed	Other
B2F4500	Authentication failed/time out	Other
B2F4400	No ECM challenge	Other
U110400	MBFM Node Absent	Other
U110500	IC Node Absent	Healed

Supplementary restraint system (5 DTCs)

DTC	Description	Status
B142A16	Battery Voltage Low	Other
U110800	IS Node Absent	Other
U205300	LATTERAL_ACCEL Signal Content Failure	Other
U205400	LONG_ACCEL Signal Content Failure	Other
U205900	YAW_RATE Signal Content Failure	Other

Main gateway module (12 DTCs)

DTC	Description	Status
U2500F1	Main Gateway Module (MGM) diagnostic CAN channel bus off	Healed
U2500F2	Main Gateway Module (MGM) body CAN channel bus off	Other
U2500F3	Main Gateway Module (MGM) multimedia CAN channel bus off	Other
U2500F4	Main Gateway Module (MGM) powertrain CAN channel bus off	Other
U2500F5	Main Gateway Module (MGM) Advanced Driver Assistance System (ADAS) CAN channel bus off	Other
U2500F6	Main Gateway Module (MGM) channel 6 bus off	Other
U2501F1	Main Gateway Module (MGM) diagnostic CAN channel bus off - ignition off	Other
U2501F2	Main Gateway Module (MGM) body CAN channel bus off - ignition off	Other
U2501F3	Main Gateway Module (MGM) multimedia CAN channel bus off - ignition off	Other
U2501F5	Main Gateway Module (MGM) Advanced Driver Assistance System (ADAS) CAN channel bus off - ignition off	Other
B140DA2	Main Gateway Module (MGM) undervoltage	Other
U135900	VIN mismatch	Other

Transmission control unit (3 DTCs)

DTC	Description	Status
P333904	TCU Internal Reset - Sudden Power OFF or External WD reset	Current
U206400	Invalid data received from Anti-lock Brake System (ABS)/Electronic Stability Program (ESP) - brake pressure signal error	Other
U20E400	Invalid Data Received From ABS/ESP Gear Hold Signal Error	Other

Head light control unit_1l (2 DTCs)

DTC	Description	Status
B14C317	ECU overvoltage	Other
B14C318	ECU undervoltage	Other

Head light control unit_2r (1 DTC)

DTC	Description	Status
B14C318	ECU undervoltage	Other

Technician Notes
2017314868

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.