

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Eritga/--
 VIN: MA3BNC22S00A30680

Odometer Reading: 39088
 License Plate: MK08CGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
 Version: V4.91

Serial Number: VB8GJCC01509
 Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	6
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	2
CGW(Central gateway control module)	1
EPS(Power steering)	0
BCM(Body Control Module)	0
SMK(Immobilizer and/or keyless system)	0

DTC (9)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (6 DTCs)

DTC	Description	Status
U0126	Lost communication with steering angle sensor module	History
C1022	Right front Wheel Speed Sensor (WSS) or encoder signal performance	History
C1036	Left rear Wheel Speed Sensor (WSS) or encoder signal performance	History
C1032	Right rear Wheel Speed Sensor (WSS) or encoder signal performance	History
C1037	Steering angle sensor power supply voltage	History
C1057	Power supply voltage	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (2 DTCs)

DTC	Description	Status
-----	-------------	--------

U0121	Lost communication with ABS or electronic stability program control module	History
B1840	Vehicle speed data invalid	History

CGW(Central gateway control module) (1 DTC)

DTC	Description	Status
U0121-87	Lost communication with ABS or electronic stability program control module	History

Technician Notes

2017304546

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.