Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/S-presso/--
VIN: MA3RFL61S00412813

Odometer Reading: 64154
License Plate: KSZ372MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	4
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	0
EPS(Power steering)	0
BCM(Body Control Module)	1
SMK(Immobilizer and/or keyless system)	1

DTC (6)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (4 DTCs)

DTC	Description	Status
C1157-1C	Power supply voltage abnormal	History
C1161-07	Pump motor circuit	History
U0401-81	CAN invalid data from ECM	History
U1082-87	Lost communication with ENG A-STOP control module	History

BCM(Body Control Module) (1 DTC)

DTC	Description	Status
B1133	Battery voltage too high	History

SMK(Immobilizer and/or keyless system) (1 DTC)

DTC	Description	Status
B1133	Battery voltage too high	History

Technician Notes

2017316616

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.