Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261014130227
Test Time: 2026-10-14 13:02:27
Technician: Trevino

2018 Honda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2018/Honda/Brio Amaze/--
VIN: MAKDF5510J4000073

Odometer Reading: 190098Km
License Plate: KG67DWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.30

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
PGM-FI	0
ABS/VSA	1
SRS/SWS/PUH	0
Gauges	0
Body Electrical ADAS	0
EPS	1
IMMOBI	0

DTC (2)

ABS/VSA (1 DTC)

DTC	Description	Status
U3006-16	Power Source Failure for ECU (Low Voltage)	Confirmed DTCs

EPS (1 DTC)

DTC	Description	Status
U3003-17	Battery voltage high	Confirmed DTCs

Technician Notes

2017312029

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.