Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--
VIN: MALA851CLGM388516

Odometer Reading: 310562
License Plate: KC87FXGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
ENG (Engine)	9
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	2
AB (Airbag)	1
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
BCM (Body Control)	0
SJB (Smart Junction Block)	4

DTC (16)

ENG (Engine) (9 DTCs)

DTC	Description	Status
P0011	Intake camshaft position (CMP) A timing over-Advanced or system performance (Bank 1)	Pending
P0080	Exhaust valve control solenoid circuit high (Bank 1)	History
P0117	Engine coolant temperature (ECT) circuit input low	History
P0118	Engine coolant temperature (ECT) circuit input high	History
P0134	Oxygen sensor circuit no activity detected (Bank 1 sensor 1)	Pending
P0204	Cylinder 4 injector circuit/open	History
P0340	Intake camshaft position (CMP) sensor 'A' circuit (Bank 1 or single sensor)	Active

P0365	Exhaust camshaft position (CMP) sensor 'B' circuit fault (Bank 1)	History
P0616	Starter relay circuit low	History

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1102	Battery voltage low	History
C1203	Right front vehicle speed sensor (VSS) circuit open or short	Active

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

SJB (Smart Junction Block) (4 DTCs)

DTC	Description	Status
B1603:00	CAN Bus off (B-CAN)	History
B2518:00	Left cornering lamp circuit short to ground	History
B2520:00	Right front turn signal lamp circuit open	History
B2521:00	Right rear turn signal lamp circuit open	History

Technician Notes

2017315982

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.