Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261023094341
Test Time: 2026-10-23 09:43:41
Technician: Boitu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i10(PA)/--
VIN: MALAN51BLHM691769

Odometer Reading: 128857
License Plate: FP02ZCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (4)

System	Status/DTC
ENG (Engine)	1
AB (Airbag)	1
IMMO (Immobilizer)	0
EPS (Motor Driven Power Steering)	0

DTC (2)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0131	Oxygen sensor circuit voltage low (Bank 1 sensor 1)	Pending

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102	Battery voltage low	History

Technician Notes

2017316371

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.