

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(BI3)/--
VIN: MALBG512LNM127149

Odometer Reading: 173111KM
License Plate: KS31DFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
ENG (Engine)	 2
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 3
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1
AVN (Audio Video Navigation)	  0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 1
RVM (Rear View Monitor)	  0

DTC (7)

ENG (Engine) (2 DTCs)

DTC	Description	Status
P0075:00	Intake valve control solenoid circuit (Bank 1)	History
P0078:00	Exhaust valve control solenoid circuit (Bank 1)	History

AB (Airbag) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2615:00	Airbag control unit (ACU) & cluster airbag lamp CAN message mismatch	History
B2617:00	Cluster airbag warning lamp CAN message timeout	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

ICU (Integrated Central Control Unit) (1 DTC)

DTC	Description	Status
B2522:00	Left front turn signal lamp circuit short to ground	History

Technician Notes
2017302333

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.