Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261021141900
Test Time: 2026-10-21 14:19:00
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(IB)/--
VIN: MALBM51BLKM516025
Odometer Reading: 182859KM
License Plate: HP32SYGP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
ENG (Engine)	0
ABS (Anti Lock Brake)	0
AB (Airbag)	1
CLU (Cluster Module)	0
A/C (Air Conditioner)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	1
BCM (Body Control)	0

DTC (2)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

Technician Notes

2017314859

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.