Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(IB)/--
VIN: MALBM51BLLM726496

Odometer Reading: 205930KM
License Plate: JK87RMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ENG (Engine)	4
ABS (Anti Lock Brake)	0
AB (Airbag)	1
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
BCM (Body Control)	0

DTC (5)

ENG (Engine) (4 DTCs)

DTC	Description	Status
P0030	Heated oxygen sensor (HO2S) Heater control circuit (Bank 1 sensor 1)	Active
P0130	Oxygen sensor circuit (Bank 1 sensor 1)	Pending
P2187	System too lean at idle (<--Additive) (Bank 1)	Active
P2191	System too lean at higher load (Multiple) (Bank 1)	Active

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2017315455

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.