Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261021092534
Test Time: 2026-10-21 09:25:34
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Creta (GS)/--
VIN: MALC381CLJM351896

Odometer Reading: 173965
License Plate: HP19TYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
ENG (Engine)	1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	1
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	1
BCM (Body Control)	0
SJB (Smart Junction Block)	0

DTC (3)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0562	System voltage low	Pending

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

Technician Notes

2017315130

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.