

TATA VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/TATA/BOLT/--
VIN: MAT623228FPRA0167

Odometer Reading: 178730
License Plate: HYG076MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V2.20

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (4)

System	Status/DTC
EMS(Engine Management System)	 9
IPC(Instrument cluster system)	 15
EPAS(Electrical power assisted steering)	 2
IMMO(Anti-theft system)	 7

DTC (33)

EMS(Engine Management System) (9 DTCs)

DTC	Description	Status
P2135-29	Throttle/pedal position sensor/switch A & B circuit range/performance - signal invalid	Memorized
P0122-14	Throttle/pedal position sensor/switch A circuit low - circuit open or short to ground	Memorized
P0121-29	Throttle/pedal position sensor/switch A circuit range/performance - signal invalid	Memorized
P2176-23	Throttle actuator control system idle position not learned - signal stuck low	Temporary
P0053-1B	HO2S heater resistance (bank 1 sensor 1) - circuit resistance above threshold	Memorized
P083F-64	Clutch pedal switch A/B correlation - signal implausible	Temporary
P0135-64	Oxygen sensor signal circuit short to heater line - signal implausible (bank 1 sensor 1)	Temporary
P0130-13	Oxygen sensor circuit open (bank 1 sensor 1)	Temporary
P060E-81	Internal control module throttle position performance - invalid serial data received	Temporary

IPC(Instrument cluster system) (15 DTCs)

DTC	Description	Status
-----	-------------	--------

U3006-16	Control module input power A circuit voltage below threshold	Temporary
U0401-81	Invalid data received from ECM	Temporary
U0100-08	Lost communication with ECM message missing	Temporary
U0100-87	DTC description not available	Temporary
U0131-87	DTC description not available	Temporary
U1309-08	Lost communication with ABS - ABS/electronic stability program - message timeout	Temporary
U0140-08	Lost communication with BCM message timeout	Temporary
U0140-87	DTC description not available	Temporary
U130B-08	Lost communication with head unit - message timeout	Temporary
U130B-87	DTC description not available	Memorized
U0151-87	DTC description not available	Temporary
U0151-08	Lost communication with restraints control module (SRS) - message timeout	Temporary
U100F-06	Ignition power mode input algorithm based failures	Temporary
B1936-56	Odometer values missing from immobilizer for learning	Temporary
B1939-86	Vehicle speed signal output implausible - signal invalid	Temporary

EPAS(Electrical power assisted steering) (2 DTCs)

DTC	Description	Status
U0101-08	DTC description not available	Confirmed
U0101-87	DTC description not available	Confirmed

IMMO(Anti-theft system) (7 DTCs)

DTC	Description	Status
B163A-14	IMMO - circuit short to ground or open	Temporary
B1636-81	IMMO - invalid serial data received	Temporary
B1636-31	IMMO - no signal	Temporary
U1614-81	Odometer storage fault - invalid serial data received	Temporary
U0028-13	Vehicle communication bus A circuit open	Memorized
U0100-87	DTC description not available	Temporary
U0100-08	DTC description not available	Temporary

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.